The Department of Ecology does NOT Warranty the Data and/or the Information on this Well Report.

File Original with Department of Ecology Second Copy - Owner's Copy Third Copy - Driller's Copy

WATER WELL REPORT

STATE OF WASHINGTON

Notice of Intent W 147 576

UNIQUE WELL I.D. # A 6-0 2 14

Water Right Permit No. 33 · ZE · 2 0 2

(1)	OWNER: Name John BUTZ / WATER ASSC. NEW RABO	ires 3315 N TRANQUILTY LN OAK HARD
(2)	LOCATION OF WELL: County Island	1E 1/4 SW 1/4 Sec 20 T 33 NR. 2 WM
(2a)	STREET ADDRESS OF WELL: (or nearest address) XX TRANGULLITY PL TAX PARCEL NO.	OAK HARSON
(3)	PROPOSED USE: Domestic Industrial Municipal Irrigation Test Well Other	(10) WELL LOG or DECOMMISSIONING PROCEDURE DESCRIPTION Formation Describe by color, character, size of material and structure, and the kind and nature of the material in each stratum penetrated, with at least one entry for each change of information. Indicate all water encountered
(4)	TYPE OF WORK: Owner's number of well (if more than one) ✓ New Well Method	MATERIAL FROM TO
	☐ Deepened ☐ Dug ☐ Bored	SAND 0 Z
	☐ Reconditioned ☐ Cable ☐ Driven ☐ Decommission	Brown Souder TT 2 6
(5)	DIMENSIONS: Diameter of well	
	Drilled 238 feet. Depth of completed well 236 ft	Gren SAJd +5, IT 12 14
(6)	CONSTRUCTION DETAILS	Gren Clay + S. IT 14 23
` '	Casing Installed:	Grey CIAY 23 45
	■ Welded	BROSN SAND 45 51.
	☐ Threaded ft toft.	Over SANOL 51 55
		aneu Clay 55 57
	Perforations: ☐ Yes ② No	BROWN SAND 57 63
	Type of perforator used	GREYSANDLY CLAY 63 75
	SIZE of perforationsin byin	Pen Gravel Leose 75 170
	perforations fromft_toft	Beaud Clay, Gravel Sand 170 195
		Grey CIAY 195 201
· · · · · · · ·	Common 771	Brown SAND 201 238
	Screens: Ryes DN DK-Pac Location 231	
	Type Model No.	Drilled In Compliance with Ice
	Diam. #35Slot Size 10 from 23, ft. to 236 ft.	8.00 Based an information
	Diam. Slot Size from ft. to ft	5.pphed by owher in
	Gravel/Filter packed: ☐ Yes ▲No ☐ Size of gravel/sand	- Dungland
	Material placed fromft. toft	
	Surface seal: Yes I No To what depth? ft Material used in seal Carrow TC	
	Oid any strata contain unusable water? Yes No	RECEIVED
	Type of water?Depth of strata	
	Method of sealing strata off	SEP 2 4 2001
7)	PUMP: Manufacturer's Name	
	آپوو·	DEPT OF ECULUIST
;	WATER LEVELS: Land surface elevation above mean sea level Static level	Work Started 7 AUG-OI Completed 14 AUG-OI
	(Cap, valve, etc)	WELL CONSTRUCTION CERTIFICATION:
,	VELL TESTS: Drawdown is amount water level is lowered below static level Vas a pump test made? ✓ Yes □ No If yes, by whom?	I constructed and/or accept responsibility for construction of this well, and compliance with all Washington well construction standards Materials us and the information reported above are true to my best knowledge and beli
	field. gal /min with ft drawdown after hrs rield gal /min with ft drawdown after hrs	Type or Print Name HALSESS License No 2480 (Licensed Driller/Engineer)
	lecovery data (time taken as zero when pump turned off) (water level measured from rell top to water level)	Trainee NameLicense No
	water Level Time Water Level Time Water Level 221 220	Orilling Company Arroganile Luxter Systems (Signed) License No 2480
-	late of test	Address 14021 BRAdshAw RX MTVERNOW
	ailer testgal /min. withft. drawdown afterhrs	Contractor's Registration No AFFORWS 10 1RJ Date 15 Sept 01
A	ırtestgal./mın withft. drawdown afterhrs rtesian flowg.p m Date	(USE ADDITIONAL SHEETS IF NECESSARY)
T	emperature of water Was a chemical analysis made? ☐Yes ☐ No	Ecology is an Equal Opportunity and Affirmative Action employer For speci
		accommodation needs contact the Water Resources Program at (260) 40

6600 The TDD number is (360) 407-6006

ECY 050-1-20 (11/98)

103062